

Vehicle Diagnostic Report

The Report is created by **LAUNCH X431**

Repair Shop

Shop Name: LegitCar Nigeria
 Address: 54 Lobito Crescent, Wuse 2, Abuja Abuja, Federal Capital Territory Nigeria
 Zip Code: 900245
 Telephone: +2347040489327
 Email: info@legitcar.ng
 SN: 989510056734
 Test Time: 2022-07-14 06:23:02



Vehicle Information

Year: 2016
 Make: TOYOTA
 Model: Camry
 VIN: 4T4BF1FK8GR541100
 Engine Size: 2AR-FE 2.5
 Odometer: 33381.00
 Vehicle Software Version: V50.40
 Diagnostic Application Version: V7.05.011
 Diagnostic path: Camry > 2016 > 2AR-FE > w/o Smart Key > Others



System fault code

The following system is abnormal:

Engine and ECT 3 problems exist

1.P0117 Engine Coolant Temperature Circuit Low Input	History
2.P1604 Startability Malfunction	History
3.P2109 Throttle/Pedal Position Sensor 'A' Minimum Stop Performance	History

ABS/VSC/TRAC 6 problems exist

1.C1201 Engine/EV Control System Malfunction	History
2.C1439 Steering Angle Sensor Initialization Incomplete	History
3.C1434 Steering Angle Sensor Output	History
4.C1433 Steering Angle Sensor Internal Circuit	History
5.C1464 Front Speed Sensor RH Circuit	History
6.C1436 Malfunction in Yaw Rate Sensor	History

EMPS 1 problem exist

1.C1528 Motor Rotation Angle Sensor	History
-------------------------------------	---------

SRS Airbag 13 problems exist

1.B1831 Open in Curtain Shield Airbag(RH)Squib Circuit	Current
2.B1836 Open in Curtain Shield Airbag(LH)Squib Circuit	Current
3.B1901 Open in Pretensioner Squib(RH)Circuit	Current
4.B1906 Open in Pretensioner Squib(LH)Circuit	Current
5.B1650 Occupant Classification System Malfunction	History
6.B1656 Seat Belt Buckle Switch(LH)	History
7.B1660 Passenger's Seat Airbag Active Mode Indicator	History
8.B1821 Open in Side Squib(RH)Circuit	History
9.B1826 Open in Side Squib(LH)Circuit	History
10.B1831 Open in Curtain Shield Airbag(RH)Squib Circuit	History
11.B1836 Open in Curtain Shield Airbag(LH)Squib Circuit	History
12.B1901 Open in Pretensioner Squib(RH)Circuit	History
13.B1906 Open in Pretensioner Squib(LH)Circuit	History

Air Conditioner 2 problems exist

1.B1479 Flow Sensor Circuit	History
2.U0100 Lost Communication With ECM/PCM/EV 'A'	History

Tire Pressure Monitor 3 problems exist

1.C2123 Transmitter ID 3 not Received(Main)	Current
2.C2123 Transmitter ID 3 not Received(Main)	History
3.C2179 Tire Pressure Monitor ECU Communication Stop	History

Combination Meter 6 problems exist

1.U0129 Lost Communication With Brake System Control Module	History
2.U0131 Lost Communication With Power Steering Control Module	History
3.U0142 Lost Communication With Body Control Module 'B'	History
4.U0151 Lost Communication With Restraints Control Module	History
5.U0163 Lost Communication With Navigation Control Module	History
6.B1507 Open in Turn Signal Circuit	History

Main Body 6 problems exist

1.B1206 Power Window Master SW ECU Communication Stop	History
2.B2321 Driver Door Motor ECU Communication Stop	History
3.U0100 Lost Communication With ECM/PCM/EV 'A'	History
4.U0101 Lost Communication with TCM	History
5.U0151 Lost Communication With Restraints Control Module	History
6.U0164 Lost Communication With HVAC Control Module	History

D-Door Motor 2 problems exist

1.B2311 Motor Malfunction	History
2.B2312 Master Switch of Driver side door Malfunction	History

Navigation System 2 problems exist

1.U0140 Lost Communication With Body Control Module

History

2.B1579 Voice Recognition Microphone Disconnected

History

The following systems are OK:

1.Cruise Control

2.Occupant Detection

3.P-Door Motor

4.Immobiliser

5.Master Switch